

Message

From: Beslow, Mike [beslow.mike@epa.gov]
Sent: 3/3/2017 7:11:35 PM
To: Dixit, Naeha [dixit.naeha@epa.gov]
CC: Riley, Ellen [riley.ellen@epa.gov]
Subject: FW: Third Party review of the 009/010 Outfalls sheen

From: Barnett, Thomas R [mailto:Thomas.Barnett@arcelormittal.com]
Sent: Friday, March 03, 2017 12:46 PM
To: Beslow, Mike <beslow.mike@epa.gov>
Cc: Fitzgerald, Sean F MST1 <Sean.F.Fitzgerald@uscg.mil>; David Greinke (DGREINKE@idem.IN.gov) <DGREINKE@idem.IN.gov>; nream@idem.IN.gov; Benoit, Simonne T <Simonne.Benoit@arcelormittal.com>; Doyle, Kevin <Kevin.Doyle@arcelormittal.com>; Mathias, Cary <cary.mathias@arcelormittal.com>
Subject: Third Party review of the 009/010 Outfalls sheen

Mike, Sean, I have talked with our Corporate folks in Cleveland, and they are going to send in an outside, third party Engineering firm to review everything we have done to date, and to review and investigate the possibility of any other potential sources of oil sheen to these two Outfalls. We have a firm we have used to this end in Ohio.

The end result will be a full report that we will convey to USEPA, the Coast Guard, and IDEM.

This will take several weeks to complete, I will update everyone on status when I come back from vacation after next week.

Thomas Barnett | Manager, Environmental Technology
ArcelorMittal Indiana Harbor LLC.
ArcelorMittal USA LLC

Environmental Department | 3001 Dickey Road, Sta. 001
East Chicago, IN 46312

T +219 399 2380 | M +219 313 1605 | F +219 399 3211 | www.arcelormittal.com